

General Information

Date & Time: 20, Jan, 2026 14:27

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	17,770
Registration No.	HAH8514	Chassis No.	PA1B18F31S4289217
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.0	117	120	117
2	Boot Lid	104.6	100	101	113
3	Roof	102.8	102	112	97/100
4	Left Front Fender	95.5	99	92	97
5	Left Front Door	101.3	102	101	101
6	Center Panel Left				
7	Left Rear Door	101.3	106	100	98
8	Left Back Panel	112.0	119	113	104
9	Right Front Fender	101.5	101	98	106
10	Right Front Door	101.3	98	103	103
11	Center Panel Right				
12	Right Rear Door	105.3	105	105	106
13	Right Back Panel	112.6	114	101	123

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Trim - Grime - Small / (L) Front Floor Mat - Grime - Medium / Ceiling - Grime - Small / Mat Other - Grime - Medium / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Medium</p>	<p>Remarks (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Large / (L) Rear Fender, Molding - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Medium / (R) Front Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Grime at trunk floor. Without warranty booklet. Incomplete tools. With spare tire, jack and seat cover. 1 key. With LTO plate.</p>