

General Information

Date & Time: 23, Jan, 2026 12:30

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	1,234
Registration No.	HAG8796	Chassis No.	PA1B18F35R4267859
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition




#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet				
2	Boot Lid				
3	Roof				
4	Left Front Fender				
5	Left Front Door				
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel				
9	Right Front Fender				
10	Right Front Door				
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel				

Overall Evaluation :

E

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	N / A
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>			
Remarks	Defects not found	Remarks	Defects not found
Frame Evaluation :	N / A	Functional Evaluation :	N / A
Remarks	Defects not found	Remarks	Defects not found

Inspector Notes
<p>Salvaged unit. No key. Damaged Front bumper, front right fender, Front right tire and bonnet. Exploded airbag. Damaged front windshield. Damaged front right underchassis. Gap at both right doors. No LTO plate.</p>