

General Information

Date & Time: 19, Jan, 2026 15:51

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	22,686
Registration No.	NHM4188	Chassis No.	PA1B18F38R4238761
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.6	116	105	111
2	Boot Lid	135.7	99	194	114
3	Roof	105.5	113	93	100/116
4	Left Front Fender	92.8	92	91	95
5	Left Front Door	93.9	94	93	95
6	Center Panel Left				
7	Left Rear Door	99.5	101	98	100
8	Left Back Panel	98.7	107	99	90
9	Right Front Fender	95.2	103	89	94
10	Right Front Door	96.7	100	91	99
11	Center Panel Right				
12	Right Rear Door	102.6	101	103	104
13	Right Back Panel	102.6	103	102	103

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / Rear Seat - Grime - Small / (L) Rear Trim - Grime - Medium / (L) Front Seat - Grime - Minimal / (L) Front Floor Mat - Grime - Small</p>	<p>Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / (L) Front Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/No spare key with reverse camera/with jack and incomplete tools/No warranty booklet/No seat cover</p>