

General Information

Date & Time: 20, Jan, 2026 16:13

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	68,018
Registration No.	NHR2265	Chassis No.	PA1B18F34P4226510
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	164.3	166	157	170
2	Boot Lid	114.3	109	112	122
3	Roof	116.6	97	110	151/108
4	Left Front Fender	99.4	102	96	100
5	Left Front Door	108.0	108	110	106
6	Center Panel Left				
7	Left Rear Door	97.8	93	105	96
8	Left Back Panel	147.6	154	143	146
9	Right Front Fender	181.0	189	174	180
10	Right Front Door	158.6	166	147	163
11	Center Panel Right				
12	Right Rear Door	112.6	123	110	105
13	Right Back Panel	168.3	165	156	184

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	D
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Medium / (L) Front Trim - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Floor Mat - Grime - Medium / (L) Front Seat - Grime - Small / Ceiling - Grime - Minimal</p>		<p>Remarks (R) Front Fender - Repair Traces - Yes / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch - Medium / Roof - Scratch & Dent - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Reverse Camera - N/A - Yes</p>	

Inspector Notes
with LTO plate, with spare tire, with jack, with spare key, no reverse camera, no warranty and manual booklet, scratches on taillight and headlight, plate light issue.