

General Information

Date & Time: 27, Jan, 2026 10:09

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	2,544
Registration No.	VAC4411	Chassis No.	PAHACACA6S6423497
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.8	97	100	118
2	Boot Lid	47.5	50	44	48
3	Roof	115.5	118	113	115/116
4	Left Front Fender	104.3	99	104	110
5	Left Front Door	97.4	94	96	103
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	60.3	63	57	61
9	Right Front Fender	103.6	103	107	101
10	Right Front Door	98.9	93	97	107
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	58.0	64	52	58

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / Ceiling - Grime - Minimal</p>	<p>Remarks (R) Side Gate - Scratch & Dent - Small / Roof - Scratch & Dent - Minimal / Rear Gate - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Side Gate - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Minimal / Bonnet, Headlight - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Cargo Bed Floor - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate, with warranty and manual booklet, with spare key, with spare tire, with incomplete tools and jack, scratches on taillight and headlight</p>