

General Information

Date & Time: 20, Jan, 2026 17:43

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	108,071
Registration No.	NHR1952	Chassis No.	PA1B18F37P4227294
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.6	118	100	111
2	Boot Lid	110.6	99	129	104
3	Roof	95.3	109	87	90/95
4	Left Front Fender	94.3	94	98	92
5	Left Front Door	97.6	99	93	101
6	Center Panel Left				
7	Left Rear Door	99.8	106	96	97
8	Left Back Panel	106.9	119	98	104
9	Right Front Fender	95.8	98	90	99
10	Right Front Door	92.6	93	90	95
11	Center Panel Right				
12	Right Rear Door	94.0	92	94	97
13	Right Back Panel	102.9	93	98	118

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Trim - Grime - Medium / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (R) Rear Trim - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Large / (L) Front Seat - Grime - Small / (L) Front Floor Mat - Cut, Crack - Medium / Ceiling - Grime - Medium / Steering Wheel - Worn, Peel, Crack - Small</p>		<p>Remarks Bonnet, Headlight - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch - Large / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch & Dent - Large / Roof - Scratch & Dent - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
<p>with LTO plate/with spare tire/No spare key/reverse camera not working/with jack and incomplete tools/right side tail light cover medium crack/No warranty booklet/plate light issue/No seat cover/possible flooding/</p>