

General Information

Date & Time: 20, Jan, 2026 13:25

Make	Toyota	Model	Hilux
YOM	2023	Odo Meter Reading	7,203
Registration No.	NIN7476	Chassis No.	MR0JB8DD1P3543989
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	124.3	125	121	127
2	Boot Lid	102.5	107	100	101
3	Roof	113.0	115	112	115/110
4	Left Front Fender	113.0	106	112	121
5	Left Front Door	112.6	117	112	109
6	Center Panel Left				
7	Left Rear Door	103.0	109	100	100
8	Left Back Panel	316.0	477	249	222
9	Right Front Fender	114.3	125	107	111
10	Right Front Door	109.3	113	109	106
11	Center Panel Right				
12	Right Rear Door	102.3	99	99	109
13	Right Back Panel	121.0	124	116	123

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Small / (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Medium / (L) Front Floor Mat - Worked - Small / (R) Front Trim - Grime - Minimal / (L) Front Trim - Grime - Medium / Ceiling - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / Glove Box - Worn, Scratch, Cut, Crack - Small / (L) Front Floor Mat - Grime - Small</p>	<p>Remarks (L) Rear Corner Panel - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Large / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Rear Gate - Scratch - Small / (L) Side Gate - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch & Dent - Large / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Large / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch & Dent - Medium / Roof - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with warranty booklet and jack and tools, no spare tire, with LTO plate, scratches on headlight and tail light, fog lamp issue</p>