


General Information

Date & Time: 22, Jan, 2026 15:44

Make	Toyota	Model	Vios
YOM	2021	Odo Meter Reading	31,977
Registration No.	NGT3905 - with MMDA Apprehension	Chassis No.	PA1B18F33M4135093
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.0	115	107	126
2	Boot Lid	121.3	120	116	128
3	Roof	100.4	109	102	93/98
4	Left Front Fender	104.0	106	102	104
5	Left Front Door	104.3	116	103	94
6	Center Panel Left				
7	Left Rear Door	108.3	111	106	108
8	Left Back Panel	109.3	102	110	116
9	Right Front Fender	107.0	101	105	115
10	Right Front Door	99.0	97	100	100
11	Center Panel Right				
12	Right Rear Door	106.6	103	109	108
13	Right Back Panel	103.5	101	100	110

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is". Any disputes shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Worn as per age - Yes / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Minimal / Ceiling - Grime - Small / (L) Front Seat - Worn - Yes</p>	<p>Remarks Member (Bolted) - Dent - Yes / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Medium / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet, with jack and tools, with spare tire, with LTO plate, scratches on tail light, with MMDA apprehension</p>