

## General Information

Date & Time: 23, Jan, 2026 15:38

<b>Make</b>	Toyota	<b>Model</b>	Fortuner
<b>YOM</b>	2021	<b>Odo Meter Reading</b>	29,775
<b>Registration No.</b>	NFC2991	<b>Chassis No.</b>	MHFCB8GS1M0520439
<b>CC</b>	2.4	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	SUV
<b>Colour</b>	Gray		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.9	98	109	102
2	Boot Lid	150.3	160	149	142
3	Roof	112.2	114	109	94/132
4	Left Front Fender	135.0	136	127	142
5	Left Front Door	107.3	113	104	105
6	Center Panel Left				
7	Left Rear Door	272.6	153	525	140
8	Left Back Panel	103.5	106	100	105
9	Right Front Fender	106.6	112	104	104
10	Right Front Door	106.6	113	103	104
11	Center Panel Right				
12	Right Rear Door	88.9	90	83	94
13	Right Back Panel	105.8	107	96	114

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

