

General Information

Date & Time: 23, Jan, 2026 12:33

Make	Toyota	Model	Wigo
YOM	2023	Odo Meter Reading	35,157
Registration No.	VAB5236L	Chassis No.	MHKA4DF5FNJ078020
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	90.5	100	92	80
2	Boot Lid	93.1	92	98	89
3	Roof	82.8	82	84	87/79
4	Left Front Fender	82.6	71	86	91
5	Left Front Door	84.3	87	84	82
6	Center Panel Left				
7	Left Rear Door	86.1	86	86	86
8	Left Back Panel	80.0	81	84	76
9	Right Front Fender	81.4	85	89	70
10	Right Front Door	84.4	83	85	86
11	Center Panel Right				
12	Right Rear Door	85.0	93	87	76
13	Right Back Panel	82.8	81	82	86

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes / Rear Seat - Grime - Medium / (R) Rear Trim - Grime - Small / (L) Rear Trim - Grime - Small / Steering Wheel - Worn, Peel, Crack - Small / Ceiling - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small	Remarks Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Medium / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Large / Roof - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes
with LTO plate/with spare tire/with 1 spare key/with jack and incomplete tools/with reverse camera/with warranty booklet /right side tail light cover issue/