


General Information

Date & Time: 26, Jan, 2026 10:33

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	2,450
Registration No.	VAC4206	Chassis No.	PA1B18F39R4243449
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.4	117	97	96
2	Boot Lid	96.1	93	96	99
3	Roof	84.9	88	84	80/88
4	Left Front Fender	90.3	91	88	92
5	Left Front Door	90.9	93	93	87
6	Center Panel Left				
7	Left Rear Door	96.2	101	94	94
8	Left Back Panel	100.5	109	97	96
9	Right Front Fender	96.2	100	93	95
10	Right Front Door	102.4	98	106	103
11	Center Panel Right				
12	Right Rear Door	98.8	90	103	104
13	Right Back Panel	100.1	96	100	105

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	B
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (R) Rear Trim - Grime - Small / (R) Front Trim - Grime - Minimal / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Small</p>		<p>Remarks (L) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / Roof - Scratch - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes</p>	

Inspector Notes
No LTO plate/with spare tire/with 1 spare key/with reverse camera/with jack and incomplete tools/with warranty booklet/No seat cover/