

General Information

Date & Time: 22, Jan, 2026 10:33

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	106,730
Registration No.	NFH1440	Chassis No.	PA1B18F35M4162540
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	96.0	102	92	95
2	Boot Lid	90.5	89	87	96
3	Roof	83.8	81	89	79/87
4	Left Front Fender	83.1	80	81	88
5	Left Front Door	86.0	90	87	81
6	Center Panel Left				
7	Left Rear Door	88.1	91	88	86
8	Left Back Panel	91.8	94	90	92
9	Right Front Fender	91.3	95	89	90
10	Right Front Door	90.6	87	89	96
11	Center Panel Right				
12	Right Rear Door	92.6	92	91	95
13	Right Back Panel	95.9	93	89	106

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Medium / Rear Seat - Grime - Medium / (R) Rear Trim - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / Steering Wheel - Worn, Peel, Crack - Medium / Ceiling - Loose, Deformed - Medium</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch - Large / (L) Front Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Scratch - Large / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch & Dent - Small / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/No spare key/reverse camera not working/plate light issue/with jack and incomplete tools/No warranty booklet/No seat cover/front ceiling loose cover/unusual sound engine</p>