

General Information

Date & Time: 27, Jan, 2026 20:03

Make	Toyota	Model	Hilux
YOM	2024	Odo Meter Reading	65,855
Registration No.	FAR8139	Chassis No.	MR0JB8DD4R3551720
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	138.3	106	112	197
2	Boot Lid	94.4	107	85	91
3	Roof	114.2	124	109	125/99
4	Left Front Fender	162.0	141	164	181
5	Left Front Door	131.0	131	123	139
6	Center Panel Left	72.3	88	64	65
7	Left Rear Door	156.3	198	140	131
8	Left Back Panel	109.6	101	111	117
9	Right Front Fender	111.0	104	109	120
10	Right Front Door	160.6	163	158	161
11	Center Panel Right	113.6	111	129	101
12	Right Rear Door	98.3	94	99	102
13	Right Back Panel	107.0	111	108	102

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / (R) Rear Trim - Grime - Small / Rear Seat - Grime - Large / (L) Front Seat - Grime - Small / Ceiling - Grime - Small</p>	<p>Remarks Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (R) Front Door, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Medium / (R) Rear Wheel, Cover - Scratch, Corrosion - Small / Rear Gate - Dent - Large / (L) Side Gate - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Roof - Modified - Large / (L) Front Fender, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with spare tire/ large crack on front windshield/ No jack and tools</p>