

## General Information

Date & Time: 20, Jan, 2026 09:39

<b>Make</b>	Toyota	<b>Model</b>	Wigo
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	12,031
<b>Registration No.</b>	GBJ3583	<b>Chassis No.</b>	MHKAA1BC8RJ032528
<b>CC</b>	1.0	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Hatchback
<b>Colour</b>	Orange		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	129.0	126	132	129
2	Boot Lid	90.4	87	96	88
3	Roof	86.8	88	78	89/93
4	Left Front Fender	94.2	85	101	97
5	Left Front Door	110.0	104	107	119
6	Center Panel Left				
7	Left Rear Door	107.3	111	109	102
8	Left Back Panel	98.8	104	94	99
9	Right Front Fender	86.0	91	84	84
10	Right Front Door	112.6	116	113	109
11	Center Panel Right				
12	Right Rear Door	107.3	98	104	120
13	Right Back Panel	95.8	96	92	100

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>C</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Floor Mat - Grime - Medium / Mat Other - Grime - Medium / (L) Front Floor Mat - Grime - Small / Ceiling - Grime - Minimal / Console, Switchs, Vents - Repair Mark - Yes</p>	<p><b>Remarks</b> Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Medium / Roof - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>C</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Warning Lamps - Issue - Yes / Battery - Weak - Yes</p>

<p><b>Inspector Notes</b></p>
<p>Maintinance warning lamp. Aircon off switch issue. With warranty booklet, spare tire, and seat cover. Without jack and tools. 2 keys. With LTO plate.</p>