

General Information

Date & Time: 22, Jan, 2026 10:48

Make	Toyota	Model	Avanza
YOM	2022	Odo Meter Reading	19,666
Registration No.	CBD8798	Chassis No.	MHFAABY1N0002443
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.0	111	108	108
2	Boot Lid	115.6	121	126	100
3	Roof	112.0	117	119	102/110
4	Left Front Fender	100.2	100	94	107
5	Left Front Door	110.0	115	100	115
6	Center Panel Left				
7	Left Rear Door	120.0	121	113	126
8	Left Back Panel	110.6	120	100	112
9	Right Front Fender	102.3	104	100	103
10	Right Front Door	105.6	110	104	103
11	Center Panel Right				
12	Right Rear Door	113.0	115	111	113
13	Right Back Panel	107.5	107	98	118

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Minimal</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>With Lto plate, with warranty booklet, with spare tire, 2keys, no jack and tools, scratches on headlights and taillights</p>