

General Information

Date & Time: 23, Jan, 2026 11:35

Make	Suzuki	Model	XL7
YOM	2025	Odo Meter Reading	6,531
Registration No.	NKP6012	Chassis No.	MHYNC32S1TJ100180
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.1	116	91	105
2	Boot Lid	91.7	82	93	100
3	Roof	98.3	81	85	91/137
4	Left Front Fender	90.5	92	86	94
5	Left Front Door	98.9	102	95	100
6	Center Panel Left				
7	Left Rear Door	100.8	113	98	91
8	Left Back Panel	95.0	104	100	81
9	Right Front Fender	94.3	102	88	93
10	Right Front Door	99.1	105	96	96
11	Center Panel Right				
12	Right Rear Door	97.1	98	95	99
13	Right Back Panel	94.1	99	88	95

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Defects not found	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
No original Lto plate, with spare tire and jack, 1key, no warranty booklet and tools, scratches on headlights and taillights