

General Information

Date & Time: 21, Jan, 2026 13:43

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	15,406
Registration No.	BAG7327	Chassis No.	PA1B18F39R4279822
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.6	122	111	111
2	Boot Lid	103.5	108	94	109
3	Roof	100.2	101	100	93/107
4	Left Front Fender	103.6	109	101	101
5	Left Front Door	100.3	98	101	102
6	Center Panel Left				
7	Left Rear Door	107.6	113	105	105
8	Left Back Panel	105.6	117	100	100
9	Right Front Fender	107.6	105	107	111
10	Right Front Door	106.6	116	104	100
11	Center Panel Right				
12	Right Rear Door	108.0	101	105	118
13	Right Back Panel	101.6	98	100	107

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : A
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes</p>	<p>Remarks (R) Front Fender, Molding - Dent - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>With Lto plate, with warranty booklet, with spare tire, with jack and tools, 3keys, scratches on headlights</p>