

General Information

Date & Time: 26, Jan, 2026 18:00

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	81,293
Registration No.	NKG8748	Chassis No.	PA1B18F31R4278826
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.1	102	96	106
2	Boot Lid	103.6	96	119	96
3	Roof	91.7	99	96	83/90
4	Left Front Fender	92.7	95	89	94
5	Left Front Door	93.9	99	92	91
6	Center Panel Left				
7	Left Rear Door	98.8	112	96	89
8	Left Back Panel	102.6	113	100	95
9	Right Front Fender	100.6	104	101	97
10	Right Front Door	104.3	105	103	105
11	Center Panel Right				
12	Right Rear Door	130.3	138	129	124
13	Right Back Panel	103.7	93	102	116

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Minimal / (R) Front Trim - Grime - Small / Rear Seat - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Minimal / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Minimal / (L) Front Floor Mat - Grime - Medium / Ceiling - Grime - Small / Overall Interior - Smell - Yes</p>	<p>Remarks (L) Front Fender, Molding - Dent - Medium / Bonnet, Headlight - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with 3 key/with jack and incomplete tools/with reverse camera/with seat cover/with warranty booklet</p>