

General Information

Date & Time: 27, Jan, 2026 16:55

Make	Suzuki	Model	Carry
YOM	2023	Odo Meter Reading	4,677
Registration No.	GBD4414	Chassis No.	MHYDC61T7PJ214858
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	120.0	128	110	122
2	Boot Lid	223.0	172	185	312
3	Roof	96.0	112	104	89/80
4	Left Front Fender	134.3	132	132	139
5	Left Front Door	183.6	192	178	181
6	Center Panel Left	152.0	109	174	173
7	Left Rear Door				
8	Left Back Panel	107.0	108	102	111
9	Right Front Fender	118.3	108	124	123
10	Right Front Door	115.3	119	117	110
11	Center Panel Right	110.0	102	121	107
12	Right Rear Door				
13	Right Back Panel	110.3	113	103	115

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal</p>	<p>Remarks (L) Front Door - Repair Traces - Yes / (L) Side Gate - Repair mark - Yes / (L) Side Gate - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Rear Gate - Scratch - Small / (R) Side Gate - Scratch - Large / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch - Small / (L) Mirror - Scratch - Small / (R) Mirror - Scratch - Minimal / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Without spare tire and jack. Incomplete tools. With warranty booklet and seat cover. 1 key. With LTO plate.</p>