

## General Information

Date & Time: 23, Jan, 2026 17:18

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	4,166
<b>Registration No.</b>	NKP9445	<b>Chassis No.</b>	PA1B18F30S4287166
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.0	112	110	105
2	Boot Lid	110.3	109	110	112
3	Roof	97.3	102	92	98/97
4	Left Front Fender	96.4	97	98	95
5	Left Front Door	92.7	93	94	91
6	Center Panel Left				
7	Left Rear Door	107.3	108	103	111
8	Left Back Panel	121.6	130	121	114
9	Right Front Fender	97.5	103	99	90
10	Right Front Door	105.0	108	101	106
11	Center Panel Right				
12	Right Rear Door	109.0	108	107	112
13	Right Back Panel	105.7	99	100	118

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>A</b>	<b>Exterior Evaluation :</b>	<b>B</b>
			
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>A</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Defects not found</p>	

<b>Inspector Notes</b>
With Lto plate, with warranty booklet, with jack and tools, 3keys, no spare tire, scratches on headlights and taillights