

General Information

Date & Time: 27, Jan, 2026 17:24

Make	Toyota	Model	Wigo
YOM	2023	Odo Meter Reading	22,848
Registration No.	GBA9714	Chassis No.	MHKAA1BC1PJ003370
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Yellow		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	126.3	125	127	127
2	Boot Lid	111.0	101	111	121
3	Roof	97.3	82	104	98/106
4	Left Front Fender	95.8	86	100	102
5	Left Front Door	113.3	108	110	122
6	Center Panel Left				
7	Left Rear Door	100.8	111	101	91
8	Left Back Panel	99.4	102	92	104
9	Right Front Fender	109.3	119	109	100
10	Right Front Door	120.3	128	107	126
11	Center Panel Right				
12	Right Rear Door	119.6	133	111	115
13	Right Back Panel	102.8	100	99	110

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Minimal / Sunvisor, Sunglass Holder - Crinkle - Minimal / (L) Front Floor Mat - Worked - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Medium</p>	<p>Remarks (L) Front Fender, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Large / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Gap at front bumper. Without warranty booklet and tools. With spare tire, jack, and seat cover. 1 key. With LTO plate.</p>