

## General Information

Date & Time: 25, Feb, 2026 15:51

<b>Make</b>	Toyota	<b>Model</b>	Innova
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	51,340
<b>Registration No.</b>	NFR9718	<b>Chassis No.</b>	PA2JA8EM9R0142467
<b>CC</b>	2.8	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Wagon
<b>Colour</b>	Red Mica Metallic		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	618.3	349	1,174	332
2	Boot Lid	109.3	118	104	106
3	Roof	95.0	108	90	89/93
4	Left Front Fender	141.6	145	155	125
5	Left Front Door	102.7	107	104	97
6	Center Panel Left				
7	Left Rear Door	105.2	112	107	97
8	Left Back Panel	125.4	102	175	99
9	Right Front Fender	128.0	119	136	129
10	Right Front Door	99.0	100	98	99
11	Center Panel Right				
12	Right Rear Door	101.8	99	100	107
13	Right Back Panel	101.3	108	101	95

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

