

General Information

Date & Time: 02, Feb, 2026 15:53

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	110,917
Registration No.	NHC1051	Chassis No.	PA1B18F3XN4192327
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.3	106	88	122
2	Boot Lid	111.0	109	112	112
3	Roof	102.0	108	101	100/99
4	Left Front Fender	97.8	104	99	90
5	Left Front Door	105.3	105	105	106
6	Center Panel Left				
7	Left Rear Door	108.5	114	112	100
8	Left Back Panel	113.3	118	103	119
9	Right Front Fender	207.6	293	165	165
10	Right Front Door	108.3	104	110	111
11	Center Panel Right				
12	Right Rear Door	111.6	103	115	117
13	Right Back Panel	108.3	107	103	115

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Trim - Grime - Medium / (R) Front Trim - Grime - Small / (L) Front Seat - Worn - Yes / (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Small / Overall Interior - Worn as per age - Yes</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (L) Rear Fender, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Medium / (L) Mirror - Scratch - Small / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch & Dent - Medium / Roof - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet, jack and tools, with spare tire, with LTO plate, scratches on tail light, plate light issue</p>