

General Information

Date & Time: 26, Jan, 2026 17:02

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	22,680
Registration No.	NHM2628	Chassis No.	PA1B18F35P4234079
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.4	104	95	97
2	Boot Lid	121.8	95	171	100
3	Roof	89.5	89	86	96/88
4	Left Front Fender	85.0	87	83	86
5	Left Front Door	91.4	98	92	85
6	Center Panel Left				
7	Left Rear Door	103.3	102	105	103
8	Left Back Panel	93.9	84	103	95
9	Right Front Fender	93.8	98	91	93
10	Right Front Door	92.5	91	92	95
11	Center Panel Right				
12	Right Rear Door	91.8	97	85	94
13	Right Back Panel	92.5	82	88	108

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / Rear Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Small</p>		<p>Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Large / Trunk Hood, Rear Gate - Repair mark - Yes / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Large / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / Roof - Scratch - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>	

Inspector Notes

with LTO plate/with spare tire/with 2 key/No reverse camera/with jack and incomplete tools/engine noisevibration/with warranty booklet/No seat cover/