

General Information

Date & Time: 03, Feb, 2026 06:05

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	20,380
Registration No.	NIN5409	Chassis No.	PA1B18F39P4207774
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.6	110	99	102
2	Boot Lid	98.1	98	96	101
3	Roof	83.8	92	87	79/78
4	Left Front Fender	91.6	91	92	92
5	Left Front Door	84.6	84	82	87
6	Center Panel Left				
7	Left Rear Door	93.9	97	92	93
8	Left Back Panel	99.4	101	94	103
9	Right Front Fender	89.3	91	86	91
10	Right Front Door	88.1	89	88	87
11	Center Panel Right				
12	Right Rear Door	89.1	83	87	98
13	Right Back Panel	90.5	90	87	94

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Small / Ceiling - Grime - Minimal / Mat Other - Missing - Yes</p>		<p>Remarks (L) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Large / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Medium / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Door, Molding - Scratch - Medium / Roof - Scratch - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Horn - Issue - Yes / Seat Belts - Issue - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate/with spare tire/No spare key/No jack and tools/No reverse camera/No seat cover/with warranty booklet/rear floor mat missing/No horn/seatbelts issue