

General Information

Date & Time: 09, Feb, 2026 15:23

Make	Toyota	Model	Wigo
YOM	2025	Odo Meter Reading	18,806
Registration No.	DBS3678	Chassis No.	MHKAA1BC4RJ028086
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.3	101	103	100
2	Boot Lid	78.9	78	82	77
3	Roof	72.9	73	66	76/76
4	Left Front Fender	92.5	89	91	98
5	Left Front Door	94.1	92	91	100
6	Center Panel Left				
7	Left Rear Door	94.0	100	91	91
8	Left Back Panel	81.9	81	82	83
9	Right Front Fender	86.9	98	85	78
10	Right Front Door	100.3	113	97	91
11	Center Panel Right				
12	Right Rear Door	94.4	97	87	100
13	Right Back Panel	86.6	87	83	89

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Missing - Yes / Rear Seat - Grime - Medium / Mat Other - Missing - Yes / (L) Front Seat - Grime - Small / (L) Front Floor Mat - Missing - Yes / Ceiling - Grime - Small</p>	<p>Remarks (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Roof - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with 2 key/incomplete tools No tools/No seat cover/with reverse camera/trunk room barrier issue/No warranty booklet</p>