

General Information

Date & Time: 18, Feb, 2026 17:32

Make	Suzuki	Model	Ertiga
YOM	2024	Odo Meter Reading	21,921
Registration No.	NOV2215	Chassis No.	MHYNC32S9RJ106950
CC	1.5	Transmission	A/T
Fuel Type	Hybrid	Type of Body	Wagon
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	94.3	91	85	107
2	Boot Lid	89.0	85	90	92
3	Roof	91.1	85	88	104/87
4	Left Front Fender	86.3	84	84	92
5	Left Front Door	99.0	101	99	97
6	Center Panel Left				
7	Left Rear Door	103.5	108	100	103
8	Left Back Panel	90.1	97	90	84
9	Right Front Fender	75.9	81	74	73
10	Right Front Door	98.3	97	95	103
11	Center Panel Right				
12	Right Rear Door	99.3	101	94	103
13	Right Back Panel	88.1	84	88	93

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Smell - Yes / Rear Seat - Grime - Small / (R) Front Seat - Grime - Large / (L) Front Floor Mat - Worked - Large</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Dent - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with spare tire and jack/ with LTO plate and warranty booklet/ with tools/</p>