

General Information

Date & Time: 10, Feb, 2026 15:14

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	19,539
Registration No.	NJF3742	Chassis No.	PA1B18F36R4278563
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.6	114	103	112
2	Boot Lid	96.3	95	94	100
3	Roof	93.5	93	94	85/102
4	Left Front Fender	99.3	102	100	96
5	Left Front Door	94.3	96	96	92
6	Center Panel Left				
7	Left Rear Door	100.7	109	99	95
8	Left Back Panel	105.3	108	105	103
9	Right Front Fender	99.4	107	96	95
10	Right Front Door	106.3	107	110	102
11	Center Panel Right				
12	Right Rear Door	106.6	107	106	107
13	Right Back Panel	107.0	102	100	119

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Mat Other - Grime - Large / Rear Seat - Grime - Medium / (L) Front Trim - Grime - Large / (L) Front Floor Mat - Worked - Small / (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Small</p>	<p>Remarks Trunk Hood, Rear Gate - Crack, Gap - Large / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Front Door, Molding - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Large / Bonnet, Headlight - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Large / Roof - Dent - Medium / (L) Front Fender, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Large / (L) Rear Fender, Molding - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet/ incomplete tools / with jack and spare tire/ with LTO plate/</p>