

General Information

Date & Time: 10, Feb, 2026 13:43

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	11,042
Registration No.	NJF7304	Chassis No.	PA1B18F30S4290438
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.0	98	124	123
2	Boot Lid	121.6	131	111	123
3	Roof	102.1	102	108	97/102
4	Left Front Fender	101.8	103	98	105
5	Left Front Door	102.2	100	101	106
6	Center Panel Left				
7	Left Rear Door	101.1	106	97	101
8	Left Back Panel	114.0	138	100	104
9	Right Front Fender	106.3	103	108	108
10	Right Front Door	103.5	100	110	101
11	Center Panel Right				
12	Right Rear Door	102.3	100	101	106
13	Right Back Panel	103.3	102	104	104

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Large / (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Medium / (L) Front Floor Mat - Worked - Large / (L) Front Trim - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Large</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no tools/ with jack and spare tire/ with LTO plate/ no warranty booklet/</p>