

General Information

Date & Time: 11, Feb, 2026 14:40

Make	Toyota	Model	Vios
YOM	2026	Odo Meter Reading	320
Registration No.	NKT7003	Chassis No.	PA1B18F33S4296203
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.6	103	99	109
2	Boot Lid	96.6	100	95	96
3	Roof	93.3	97	99	85/93
4	Left Front Fender	95.7	95	95	98
5	Left Front Door	96.0	101	98	89
6	Center Panel Left				
7	Left Rear Door	97.8	100	100	94
8	Left Back Panel	97.7	100	96	97
9	Right Front Fender	95.9	98	94	97
10	Right Front Door	98.5	93	102	101
11	Center Panel Right				
12	Right Rear Door	93.3	89	93	98
13	Right Back Panel	95.0	89	94	102

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : A
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Small / (R) Front Trim - Grime - Minimal / Rear Seat - Grime - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes</p>	<p>Remarks Bonnet, Headlight - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with 2 key/No jack and tools/with reverse camera/No seat cover/with warranty booklet/battery weak</p>