

General Information

Date & Time: 26, Jan, 2026 14:44

Make	Toyota	Model	Veloz
YOM	2025	Odo Meter Reading	14,069
Registration No.	DBT9797	Chassis No.	MHFAB1BY9S3136706
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Wagon
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.0	109	102	113
2	Boot Lid	108.6	106	120	100
3	Roof	128.7	140	135	121/119
4	Left Front Fender	113.6	117	113	111
5	Left Front Door	125.0	124	124	127
6	Center Panel Left				
7	Left Rear Door	118.0	121	120	113
8	Left Back Panel	139.0	152	126	139
9	Right Front Fender	129.3	118	121	149
10	Right Front Door	123.6	124	123	124
11	Center Panel Right				
12	Right Rear Door	134.3	157	121	125
13	Right Back Panel	146.0	138	135	165

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Minimal / Ceiling - Grime - Small / Rear Seat - Grime - Minimal</p>	<p>Remarks (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Repair mark - Yes / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Lamps (Brake, Tail, Fog) - Issue - Yes</p>

<p>Inspector Notes</p>
<p>with warranty booklet, jack and tools, with spare tire and LTO PLATE, scratches on tail light, dome light issue</p>