

## General Information

Date & Time: 06, Feb, 2026 08:45

<b>Make</b>	Toyota	<b>Model</b>	Avanza
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	12,982
<b>Registration No.</b>	NHU9106	<b>Chassis No.</b>	MHFAA1BY2R0035098
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	MPV
<b>Colour</b>	Red Mica Metallic		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	94.7	91	96	97
2	Boot Lid	94.4	88	103	93
3	Roof	108.5	112	122	100/100
4	Left Front Fender	94.1	98	88	97
5	Left Front Door	111.6	106	112	117
6	Center Panel Left				
7	Left Rear Door	104.6	105	100	109
8	Left Back Panel	117.0	120	115	116
9	Right Front Fender	95.8	101	96	91
10	Right Front Door	109.6	113	108	108
11	Center Panel Right				
12	Right Rear Door	105.3	110	101	105
13	Right Back Panel	103.8	94	110	108

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

