

General Information

Date & Time: 02, Feb, 2026 14:18

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	26,340
Registration No.	CCA9241	Chassis No.	PA1B18F32R4262974
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.6	116	101	118
2	Boot Lid	120.3	111	118	132
3	Roof	114.0	109	118	115/114
4	Left Front Fender	114.0	112	112	118
5	Left Front Door	109.0	108	106	113
6	Center Panel Left				
7	Left Rear Door	113.0	117	111	111
8	Left Back Panel	118.3	117	124	114
9	Right Front Fender	115.6	121	111	115
10	Right Front Door	133.0	118	166	115
11	Center Panel Right				
12	Right Rear Door	127.6	134	118	131
13	Right Back Panel	119.3	111	115	132

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	D
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Medium / Trim Other - Grime - Medium / (L) Front Floor Mat - Grime - Medium / (L) Front Trim - Grime - Medium / (R) Front Trim - Grime - Small / Ceiling - Grime - Minimal</p>		<p>Remarks (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / Roof - Scratch & Dent - Small / Bonnet, Headlight - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate, with spare tire, with incomplete tools and jack, with reverse camera, scratches on taillight and headlight, issue on side mirror right side, no spare key.