

General Information

Date & Time: 03, Feb, 2026 08:55

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	14,182
Registration No.	CCA9935	Chassis No.	PA1B18F33R4263650
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.3	113	96	110
2	Boot Lid	103.5	96	103	112
3	Roof	99.4	102	106	92/98
4	Left Front Fender	95.3	100	94	92
5	Left Front Door	98.5	101	97	98
6	Center Panel Left				
7	Left Rear Door	98.5	100	98	97
8	Left Back Panel	104.3	112	101	100
9	Right Front Fender	98.0	98	95	101
10	Right Front Door	102.6	108	100	100
11	Center Panel Right				
12	Right Rear Door	94.8	91	93	101
13	Right Back Panel	107.3	105	100	117

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : D	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Worked - Large / (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Worked - Large / (L) Front Seat - Grime - Large / Dashboard - Traces of Adhesive Tape - Yes / Rear Seat - Grime - Large</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / (R) Front Door, Molding - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch & Dent - Large / Bonnet, Headlight - Crack, Gap - Small / (R) Front Fender, Molding - Dent - Medium / (L) Front Fender, Molding - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>incomplete tools/ with spare tire and jack/ with warranty booklet and LTO plate/</p>