

General Information

Date & Time: 04, Feb, 2026 08:20

Make	Toyota	Model	Wigo
YOM	2022	Odo Meter Reading	82,415
Registration No.	DAR8784	Chassis No.	MHKA4DF5FNJ071654
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.2	92	103	100
2	Boot Lid	102.2	95	113	99
3	Roof	90.5	85	89	101/87
4	Left Front Fender	96.5	93	100	97
5	Left Front Door	96.4	98	100	91
6	Center Panel Left				
7	Left Rear Door	94.2	90	93	100
8	Left Back Panel	98.6	104	102	90
9	Right Front Fender	99.2	104	100	94
10	Right Front Door	97.0	95	98	99
11	Center Panel Right				
12	Right Rear Door	94.2	100	95	88
13	Right Back Panel	96.4	99	88	102

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Rear Seat - Grime - Large / (R) Front Seat - Grime - Large / (R) Front Floor Mat - Worked - Large / (L) Front Floor Mat - Worked - Large</p>		<p>Remarks Bonnet, Headlight - Scratch - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Medium / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Small / (R) Rear Fender, Molding - Crack, Gap - Medium</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
no tools and jack/ no warranty booklet/with spare tire and LTO plate/