

General Information

Date & Time: 28, Jan, 2026 15:21

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	7,393
Registration No.	DBR8477	Chassis No.	PA1B18F31R4278874
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.6	116	111	123
2	Boot Lid	111.0	107	111	115
3	Roof	104.2	107	102	103/105
4	Left Front Fender	108.6	108	109	109
5	Left Front Door	108.6	109	110	107
6	Center Panel Left				
7	Left Rear Door	115.3	121	116	109
8	Left Back Panel	116.3	119	117	113
9	Right Front Fender	103.3	104	105	101
10	Right Front Door	108.3	111	106	108
11	Center Panel Right				
12	Right Rear Door	110.6	104	104	124
13	Right Back Panel	111.0	108	105	120

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Dent - Small / (L) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>no tools and jack / with LTO plate and warranty booklet/ with spare tire</p>