

General Information

Date & Time: 03, Feb, 2026 07:41

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	11,101
Registration No.	NKQ3267	Chassis No.	PAHACACA0S6423883
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.8	100	103	103
2	Boot Lid	45.0	51	39	45
3	Roof	107.8	107	124	101/99
4	Left Front Fender	96.7	93	96	101
5	Left Front Door	95.1	95	99	91
6	Center Panel Left	76.4	78	63	89
7	Left Rear Door				
8	Left Back Panel	56.0	58	63	47
9	Right Front Fender	98.7	101	96	100
10	Right Front Door	95.1	91	96	99
11	Center Panel Right	79.3	62	75	101
12	Right Rear Door				
13	Right Back Panel	49.3	54	48	46

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Grime - Medium / Ceiling - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Center Panel - Scratch - Minimal / (R) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Small / Rear Gate - Scratch & Dent - Small / (L) Side Gate - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Cab Back Panel - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Cargo Bed Floor - Scratch & Dent - Large</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>with warranty booklet, jack and tools, with spare tire, with one LTO plate and one modified plate, scratches on tail light</p>