

General Information

Date & Time: 27, Jan, 2026 16:16

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	25,154
Registration No.	JAS7544	Chassis No.	PA1B18F31R4268667
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.0	110	109	102
2	Boot Lid	105.3	101	104	111
3	Roof	100.2	103	104	99/95
4	Left Front Fender	91.7	93	93	89
5	Left Front Door	108.0	106	112	106
6	Center Panel Left				
7	Left Rear Door	107.3	113	108	101
8	Left Back Panel	112.3	123	109	105
9	Right Front Fender	100.7	105	97	100
10	Right Front Door	102.4	106	96	105
11	Center Panel Right				
12	Right Rear Door	102.1	106	98	103
13	Right Back Panel	106.0	103	100	115

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Small / Ceiling - Grime - Small / Rear Seat - Grime - Medium / Mat Other - Grime - Medium / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Small</p>	<p>Remarks Bonnet, Headlight - Scratch - Medium / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Door, Molding - Scratch & Dent - Large / (L) Rear Wheel, Cover - Cap Missing - Yes</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Parking brake cover issue. With warranty booklet, spare tire and jack. Incomplete tools. Without seat cover. 1 key. With LTO plate.</p>