

General Information

Date & Time: 26, Jan, 2026 18:34

Make	Toyota	Model	Vios
YOM	2026	Odo Meter Reading	1,888
Registration No.	CCQ4945	Chassis No.	PA1B118F39S4297114
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.3	119	107	114
2	Boot Lid	117.6	125	109	119
3	Roof	100.8	103	99	99/103
4	Left Front Fender	104.3	100	107	106
5	Left Front Door	102.8	108	100	101
6	Center Panel Left				
7	Left Rear Door	105.3	108	107	101
8	Left Back Panel	104.3	104	101	108
9	Right Front Fender	110.3	111	110	110
10	Right Front Door	106.3	104	107	108
11	Center Panel Right				
12	Right Rear Door	107.3	106	101	115
13	Right Back Panel	110.0	108	110	112

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Defects not found	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
With Lto plate ,with warranty booklet,3keys, no spare tire, no jack and tools ,scratches on headlights