

General Information

Date & Time: 26, Jan, 2026 16:32

Make	Toyota	Model	Wigo
YOM	2025	Odo Meter Reading	13,727
Registration No.	DBT4219	Chassis No.	MHKAA1BC3RJ34252
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Orange		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.6	119	126	126
2	Boot Lid	93.6	93	96	92
3	Roof	82.3	81	76	80/93
4	Left Front Fender	99.6	100	100	99
5	Left Front Door	101.2	92	97	115
6	Center Panel Left				
7	Left Rear Door	103.0	112	95	102
8	Left Back Panel	94.0	102	89	91
9	Right Front Fender	92.3	105	96	77
10	Right Front Door	104.8	114	101	99
11	Center Panel Right				
12	Right Rear Door	95.5	85	91	110
13	Right Back Panel	84.4	83	84	87

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Defects not found	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
With Lto plate, with warranty booklet, with spare tire and jack, 2keys, no tools, scratches on headlights and taillights