

## General Information

Date & Time: 03, Feb, 2026 14:38

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	15,560
<b>Registration No.</b>	HAG8631	<b>Chassis No.</b>	PA1B18F36R4268678
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Black		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.0	107	106	108
2	Boot Lid	104.3	101	103	109
3	Roof	103.0	103	112	96/101
4	Left Front Fender	90.5	90	92	90
5	Left Front Door	102.0	105	101	100
6	Center Panel Left				
7	Left Rear Door	102.1	111	98	97
8	Left Back Panel	108.6	117	109	100
9	Right Front Fender	99.1	102	96	100
10	Right Front Door	99.9	100	100	100
11	Center Panel Right				
12	Right Rear Door	104.3	107	100	106
13	Right Back Panel	109.0	108	103	116

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>B</b>	<b>Exterior Evaluation :</b>	<b>E</b>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Grime - Medium / Mat Other - Grime - Small / Ceiling - Grime - Small / (R) Front Trim - Grime - Medium / (R) Front Floor Mat - Grime - Small</p>		<p><b>Remarks</b> (L) Front Fender, Molding - Scratch - Medium / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch &amp; Dent - Large / (L) Rear Door, Molding - Scratch - Medium / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large</p>	
<b>Frame Evaluation :</b>	<b>C</b>	<b>Functional Evaluation :</b>	<b>A</b>
<p><b>Remarks</b> Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes</p>		<p><b>Remarks</b> Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
<p>Large scratch at left head light. Gap at front bumper. Without warranty booklet. Incomplete tools. With spare tire, jack and seat cover. 1 key. With LTO plate.</p>