

General Information

Date & Time: 10, Feb, 2026 06:50

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	17,368
Registration No.	GBJ8496	Chassis No.	PAHACACA9S6421307
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Dropside
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	91.3	99	85	91
2	Boot Lid	58.9	59	56	61
3	Roof	113.7	140	108	97/110
4	Left Front Fender	87.0	83	94	85
5	Left Front Door	89.8	91	90	89
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	56.3	48	69	51
9	Right Front Fender	90.9	88	95	89
10	Right Front Door	85.7	81	87	89
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	51.7	45	68	43

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	B
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Ceiling - Grime - Small / (R) Front Seat - Grime - Minimal / (L) Front Seat - Grime - Small</p>		<p>Remarks Roof - Rust, Corrosion - Medium / Rear Gate - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Cargo Bed Floor - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / (L) Front Fender, Molding - Scratch - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
No LTO plate. with spare tire. no spare key. no seat cover. no warranty booklet. without jack and tools