

General Information

Date & Time: 30, Jan, 2026 06:42

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	8,083
Registration No.	GBK5857	Chassis No.	PA1B18F3XS4289717
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.9	110	99	109
2	Boot Lid	106.0	107	101	110
3	Roof	97.9	102	96	94/100
4	Left Front Fender	92.7	95	92	91
5	Left Front Door	103.3	95	109	106
6	Center Panel Left				
7	Left Rear Door	100.8	112	95	95
8	Left Back Panel	104.4	111	104	98
9	Right Front Fender	109.5	105	96	128
10	Right Front Door	126.3	108	104	167
11	Center Panel Right				
12	Right Rear Door	99.5	99	96	104
13	Right Back Panel	98.1	94	96	105

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Small / Rear Seat - Grime - Medium</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / Bonnet, Headlight - Scratch - Medium / (L) Front Fender, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with spare tire/ with warranty booklet/ No spare key/with seat cover/with jack and tools</p>