

## General Information

Date & Time: 30, Jan, 2026 06:35

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	9,434
<b>Registration No.</b>	FAT5805	<b>Chassis No.</b>	PA1B18F32S4289792
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	125.7	177	99	101
2	Boot Lid	99.5	100	95	104
3	Roof	92.6	96	87	88/100
4	Left Front Fender	96.6	96	98	97
5	Left Front Door	90.3	89	89	93
6	Center Panel Left				
7	Left Rear Door	96.4	100	96	94
8	Left Back Panel	107.2	112	110	100
9	Right Front Fender	106.7	105	98	117
10	Right Front Door	99.2	106	94	98
11	Center Panel Right				
12	Right Rear Door	99.8	93	99	108
13	Right Back Panel	102.9	97	100	112

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	A	<b>Exterior Evaluation :</b>	B
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (R) Front Seat - Grime - Small / (L) Front Trim - Grime - Minimal / Rear Seat - Grime - Minimal</p>		<p><b>Remarks</b> Bonnet - Repair Traces - Yes / Front Bumper, Grille, Lamps - Modified - Medium / (R) Rear Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	A
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Defects not found</p>	

<b>Inspector Notes</b>
with spare tire. with tools no jack. with seat cover. with 2 spare keys. no warranty booklet