


General Information

Date & Time: 02, Feb, 2025 07:57

Make	Toyota	Model	Vios
YOM	2021	Mileage	31,711
Registration No.	NFC2352	Chassis No.	PA1B18F33M4145493
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.0	104	106	111
2	Boot Lid	105.6	101	105	111
3	Roof	98.2	106	94	88/105
4	Left Front Fender	99.3	97	91	110
5	Left Front Door	100.9	108	100	95
6	Center Panel Left				
7	Left Rear Door	106.0	108	102	108
8	Left Back Panel	104.6	108	104	102
9	Right Front Fender	96.7	104	88	98
10	Right Front Door	102.6	105	97	106
11	Center Panel Right				
12	Right Rear Door	101.0	95	107	101
13	Right Back Panel	104.8	96	105	113

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium / (L) Front Floor Mat - Grime - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Door, Molding - Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

no spare tire/ no warranty booklet/ with jack and tools/ with LTO plate/ worn tires