

General Information

Date & Time: 03, Feb, 2026 18:37

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	12,835
Registration No.	DBT6358	Chassis No.	PA1B18F3XS4283982
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.6	94	100	117
2	Boot Lid	109.3	106	101	121
3	Roof	98.3	100	100	94/100
4	Left Front Fender	100.2	101	100	100
5	Left Front Door	98.8	98	101	98
6	Center Panel Left				
7	Left Rear Door	109.6	107	100	122
8	Left Back Panel	109.0	119	104	104
9	Right Front Fender	106.7	114	96	110
10	Right Front Door	102.6	100	104	104
11	Center Panel Right				
12	Right Rear Door	105.6	109	102	106
13	Right Back Panel	101.6	98	95	112

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Floor Mat - Cut, Crack - Medium / (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / Ceiling - Grime - Minimal</p>		<p>Remarks Roof - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Spare Key - Issue - Unexist</p>	

Inspector Notes
with LTO plate, with spare tire, with jack, with reverse camera, no spare key, no warranty and manual booklet, scratches on taillight and headlight .