

General Information

Date & Time: 02, Feb, 2025 15:33

Make	Toyota	Model	Wigo
YOM	2023	Mileage	47,159
Registration No.	DAS8410	Chassis No.	MHKA4DF5FNJ074984
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Orange		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	92.7	94	104	81
2	Boot Lid	96.0	99	98	92
3	Roof	81.2	77	90	78/81
4	Left Front Fender	89.6	86	91	92
5	Left Front Door	85.9	86	88	84
6	Center Panel Left				
7	Left Rear Door	86.0	92	84	82
8	Left Back Panel	86.2	92	87	79
9	Right Front Fender	100.7	103	101	98
10	Right Front Door	86.8	85	93	82
11	Center Panel Right				
12	Right Rear Door	88.7	87	92	88
13	Right Back Panel	94.2	96	94	93

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Mat Other - Missing - Yes / (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / (L) Front Seat - Grime - Small / Rear Seat - Grime - Large / Trunk Room - Loose, Deformed - Large	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / (R) Front Door, Molding - Dent - Minimal / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / Roof - Dent - Small / (L) Mirror - Scratch - Small / (L) Rear Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist

Inspector Notes
no warran5y booklet/ no sparetire/ no tools/ no jack/ adhesive marks on both side mirrors/ with LTO plate/