

General Information

Date & Time: 03, Feb, 2026 07:56

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	18,778
Registration No.	EAJ8299	Chassis No.	PA1B18F33R4275944
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.2	114	93	109
2	Boot Lid	95.8	90	96	101
3	Roof	84.2	85	82	84/85
4	Left Front Fender	86.7	89	83	88
5	Left Front Door	87.0	88	89	84
6	Center Panel Left				
7	Left Rear Door	89.4	96	88	84
8	Left Back Panel	98.8	104	95	98
9	Right Front Fender	94.3	99	88	95
10	Right Front Door	88.1	87	86	91
11	Center Panel Right				
12	Right Rear Door	90.9	93	89	91
13	Right Back Panel	92.8	90	85	103

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small / Rear Seat - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Small</p>	<p>Remarks Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Large / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch - Small / Member (Bolted) - Rust, Corrosion - Yes</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with 1 spare key/with jack No tools/No seat cover/with reverse camera/No warranty booklets/bonnet hood traces of adhesive tape/fog light issue</p>