

General Information

Date & Time: 02, Feb, 2026 16:03

Make	Toyota	Model	Fortuner
YOM	2024	Odo Meter Reading	39,679
Registration No.	NFR6728	Chassis No.	MHFCB3GS3R0495831
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.0	109	125	111
2	Boot Lid	102.8	101	112	96
3	Roof	120.5	119	127	132/104
4	Left Front Fender	134.0	135	114	153
5	Left Front Door	111.3	110	119	105
6	Center Panel Left				
7	Left Rear Door	100.5	102	105	95
8	Left Back Panel	110.6	112	109	111
9	Right Front Fender	109.0	113	107	107
10	Right Front Door	100.3	100	101	100
11	Center Panel Right				
12	Right Rear Door	100.5	97	102	103
13	Right Back Panel	121.6	138	117	110

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Medium / (R) Rear Trim - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Minimal / (L) Rear Trim - Grime - Medium / (R) Front Seat - Grime - Minimal / (L) Front Seat - Worn - Yes / (L) Front Floor Mat - Worked - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with warranty booklet, no jack and tools, with spare tire, with LTO plate, scratches on tail light</p>