

General Information

Date & Time: 03, Feb, 2026 17:29

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	11,724
Registration No.	NHH6976	Chassis No.	PA1B18F31R4242733
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.0	109	107	117
2	Boot Lid	108.3	106	106	113
3	Roof	100.8	101	105	94/103
4	Left Front Fender	99.5	98	97	104
5	Left Front Door	103.9	100	105	107
6	Center Panel Left				
7	Left Rear Door	102.1	107	98	101
8	Left Back Panel	108.0	114	106	104
9	Right Front Fender	98.3	100	97	98
10	Right Front Door	102.3	107	100	100
11	Center Panel Right				
12	Right Rear Door	98.0	92	95	108
13	Right Back Panel	106.3	105	101	113

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Large</p>	<p>Remarks (R) Front Fender, Molding - Crack, Gap - Medium / (R) Front Door, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>incomplete tools/ with jack and spare tire/ with warranty booklet and LTO plate</p>